

**PRODUCT INFORMATION**

<b>Style:</b>	<b>1881</b>		
<b>Sizing:</b>	<u>Size</u>	<u>Part #</u>	<u>Overedge</u>
	Small	1881S	Yellow
	Medium	1881M	Blue
	Large	1881L	White
	XLarge	1881XL	Orange
<b>Registered Brand Name:</b>	Whizard®		
<b>Classification:</b>	Cut Resistant		



**PRODUCT DESCRIPTION**

<b>Description:</b>	Metalguard® Heavy Weight PVC Dots
<b>Color:</b>	Green and Yellow
<b>Material:</b>	Continuous Heavy Weight Shell with PVC Coated Fingertips and Palm
<b>Palm:</b>	PVC Dots
<b>Gauge:</b>	7
<b>Sold by:</b>	Dozen Pair
<b>Packaging (Inner Pack):</b>	3 Pairs
<b>Packaging (Case Pack):</b>	36 Pairs

**CUT PROTECTION PERFORMANCE INFORMATION**

<b>Test Method:</b>	ASTM F1790-97
<b>Test Results:</b>	3679 grams / 8.10 lbs. ANSI Level 5
<b>Test Method:</b>	ASTM F2992-15
<b>Test Results:</b>	3484 grams ANSI Level A6

**ABRASION PROTECTION PERFORMANCE INFORMATION**

<b>Test Method:</b>	ASTM D3884-09
<b>Test Results:</b>	ANSI Level 3 1236 Cycles

**WASHING INSTRUCTIONS**

Remove all large particles. Rinse with cold water then machine wash in warm water with mild detergent or soap for 10-15 minutes. Water temperature should not exceed 160°F (71°C). Rinse in cold water. Tumble dry for 10-15 minutes, not exceeding 150°F (67°C). Do not use bleach or dry cleaning solution.

**CAUTION**

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial  
Toll-Free 1.800.247.3295 www.wellslamontindustrial.com